




## M40 FIVE - A-Frame



**2x Inner Leg**

**2x Outer Leg**

**1x Head A**

**1x Head B**

**2x Head Spacer**

**2x Sphere Foot**

**2x M10 Bolt(100mm), Washer & Nut**

**6x M10x85 Quick Pins**

**2x M6x8 Bolt and Barrel Nut (Feet)**

**2x Wire Lock Pins (Legs)**

**1x 12ft - 3.5m Hobble Strap**

Please be aware that this page does not replace the official product manual. It is the first revision of what we call a cheat sheet. This sheet is meant to be a convenient reference page of necessary components per configuration, an image of the configuration, and a non-exhaustive tips sections, to assist you while on the field working. It should be used at your own discretion. It is crucial to understand that the information provided here is suggestive and not definitive, and it does not substitute for proper training.

### NOTES:

**Rig on the ground, away from the edge.**


**Use as is shown or as a Sideways A-frame.**

**Keep an eye out for resulting forces and make sure the feet are tied off.**

**Tipping to be tested before use.**

**Rigging option: Add Rigging hubs to legs, use Rigging Tube to fit the large dia Rig Hub.**

### Experience Level 3



Resultant load remains in same plane as A-frame